

RC10GT PERFORMANCE UPDATE:

We improved the performance of the Sport Gas Truck by making a parts change inside the transmission. The picture to the right replaces Fig. 67 of your manual. It shows that we have replaced the two center #6599 bushings with the new #7659 idler gear shaft ball bearings.

BRONZE #6599
3/16 x 3/8
unflanged bushing



SILVER #7659
3/16 x 3/8
unflanged bearing



BRONZE #6598
3/8 x 5/8
unflanged bushing

